
Appl. No. 10/575,365 Docket No. Q78082 Filed: April 11, 2006 Reply to Office Action of May 28, 2008 Replacement Sheet



1 Flip-Chip-Type Light-Emitting Dovice
2 Au Bump
3 Submount
4 Au Wire
5 70-18 Stim

Fig. 3